

PIPE UNION (PU)

Model Selection Chart

With Screwed Ends					
Sr. No.	End Conn 1 Thread type NPT Female	End Conn 2 Thread type NPT Female	Model No. For MOC: SS316		
1	1/4"	1/4"	SS-PU-4F-3000		
2	3/8"	3/8"	SS-PU-6F-3000		
3	1/2"	1/2"	SS-PU-8F-3000		
4	3/4"	3/4"	SS-PU-12F-3000		
5	1"	1"	SS-PU-16F-3000		
6	1-1/4"	1-1/4"	SS-PU-20F-3000		
7	1-1/2"	1-1/2"	SS-PU-24F-3000		
8	2"	2"	SS-PU-32F-3000		

With Socket Weld Ends

Sr. No.	End Conn 1 Socket Weld	End Conn 2 Socket Weld	Model No. For MOC: SS316
9	1/4"	1/4"	SS-PU-4SW-3000
10	3/8"	3/8"	SS-PU-6SW-3000
11	1/2"	1/2"	SS-PU-8SW-3000
12	3/4"	3/4"	SS-PU-12SW-3000
13	1"	1"	SS-PU-16SW-3000
14	1-1/4"	1-1/4"	SS-PU-20SW-3000
15	1-1/2"	1-1/2"	SS-PU-24SW-3000
16	2"	2"	SS-PU-32SW-3000



Material Grade Selection Chart			
For following Material Grade (MOC)	Replace First Two Letters of Model No. with following		
SS316L	SSL		
SS304	S4		
SS304L	S4L		
Brass	В		
Alloy 400	ML		
Alloy 600	INC		
Alloy C276	HC		
Carbon Steel	CS		
Note: Above Model Nos are for 2000# only. For 6000# & 9000# change 3000 in Model No to the class required			

"TRUEWAY HOUSE", Plot No. 535/14-15, Sonawala Cross Road No. 2, Nr. M.K. Industrial Estate, Goregaon (East),

Mumbai - 400 063, INDIA. Mobile: +91 9321756212, +91 9004146034 | Phone: +91 22 26852241, 26851052.

E-mail

Head Office

sales@truewayindia.in

Website

www.truewayindia.in

